

Every electronic instrument needs periodic calibration to compensate for component drift due to aging. The Cadex Analyzer Voltage Calibration Kit offers a do-it-yourself method that is economical, quick and easy. For ISO9000 users, this kit includes a renewable calibration certificate that is valid for three years from the date of purchase and is traceable to a national standard.

Voltage Calibration Kit

This kit calibrates the following Cadex and Motorola C7x00 Battery Analyzers:

- C7000, C7000ER firmware version V3.02 and above
- C7200, C7400 all firmware versions
- Motorola BOS, BOSII all firmware versions

If necessary, contact your sales representative to obtain a firmware upgrade

The kit consists of

Four Voltage Calibration Adapters	Part No. 07-130-0000
One C7x00 Calibration Guide	Part No. 89-204-1017
One Certificate of Calibration	This certificate ensures that the analyzer calibration is traceable
	to a national standard. This certificate is valid for three years, is
	renewable and covers all analyzers that are calibrated.

C7x00 Voltage Calibration Procedure

- 1. Turn ON the analyzer.
- 2. When the global screen is displayed, firmly insert the Voltage Calibration Adapters, one in each station (the C7200 battery analyzer requires only two Voltage Calibration Adapters).
- 3. Press the MENU key.
- 4. Scroll to SYSTEM SETUP using the key (On C7000/ER or BOS use S1 key) and press ENTER.
- 5. a. C7200, C7400, BOSII: scroll to 'Calibrate Voltage'.
 - b. C7000, C7000ER, BOS: scroll to 'Calibration', press ENTER scroll to 'Voltage Calibration.'
- 6. Press ENTER to begin calibration. The calibration process takes about 5 seconds.
- 7. Remove the Voltage Calibration Adapters when instructed on the screen.
- 8. Press the Menu key to return to the Global screen.
- 9. Press and release the Fn key, then press the number 7 to display the startup screen. The "#" should appear in the upper right corner to indicate a successful calibration.
- 10. The C7x00 is now voltage calibrated.
- 11. Perform Adapter/Station Calibration. Refer to the C7x00 Users Manual for adapter/station calibration instructions.

Maintaining Calibration

- **Voltage Calibration**: Using this kit, calibrate the C7x00 once a year to maintain performance specifications.
- Adapter/Station Calibration: Refer to the C7x00 Users Manual for information on maintaining adapter calibration.
- Recalibrating the Voltage Calibration Adapters: Return the voltage calibration kit to the factory
 every three years for recalibration and recertification. Contact Cadex or e-mail
 service@cadex.com for a cost estimate and a Return Authorization.